
















GOODYEAR PART NO.	Side View With Extended and Compressed Height	Upper Mounting View	Lower Mounting View	Replaces These Springs
1R11-201 Flexmember 566-22-3-021 Piston 566-20-7-252 Composite		ASA-92-8-017 		Firestone 9377 Reyco 21054-01 Triangle 8478
1R11-202 Flexmember 566-22-3-021 Piston 566-20-7-252 Composite		ASA-92-8-164 		Firestone 9378 Ridewell 1003589378C Triangle 8447
1R11-203 Flexmember 566-22-3-021 Piston 566-20-7-251 Composite		ASA-92-8-164 		Firestone 9387 Ridewell 1003589387C Triangle 8479
1R11-204 Flexmember 566-22-3-021 Piston 566-20-7-253 Composite		ASA-92-8-164 		Firestone 8900 Reyco 17361-01 Triangle 8401
1R11-205 Flexmember 566-22-3-021 Piston 566-20-7-253 Composite		ASA-92-8-017 		Firestone 9476 Reyco 20446-01 Triangle 8516