









ROLLING LOBE STYLE

| GOODYEAR PART NO. | Side View With Extended and Compressed Height | Upper Mounting View | Lower Mounting View | Replaces These Springs |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <p>1R12-090 - Tapped Hole on Top Retainers 3/8-16, on Piston</p> <p>Flexmember 566-24-3-038</p> <p>Piston 566-20-7-079 Steel</p> |  <p>1R12-090</p> | <p>AS1-92-8-052</p>  |  | <p>Dayton 352-9213 Firestone 9213 Load Guard SC2048 Navistar 1660581C1 501559C1 501599C2 Triangle 8407</p> |
| <p>1R12-092</p> <p>Flexmember 566-24-3-038</p> <p>Piston 566-20-7-080 Composite</p> |  <p>1R12-092</p> | <p>ASA-92-8-164</p>  |  | <p>Dayton 517559C9 352-9082 Fab Tek 101828 Firestone 9082 9228 Granning 2727 HDA PMABG9082 B Hendrickson B-2066 36514-7 Hutchens 9630-01 Kelderman Kwikk Lock / Todco CP-3281 CP-5125 CP-5152 Load Guard SC2035 Navistar</p> <p>Neway 90557006 90557027 90557037 90557054 90557075 R&S Truck 1090217 Reyco 12882-01 Ridewell 1003589082C Silent Drive Susp., Inc. 201869 Taurus AS506-9082 Toyo TRL240/393 Triangle 8310 Watson & Chalin AS-0011</p> |
| <p>1R12-093 Service Assy. for 1R12-092</p> <p>Flexmember 566-24-3-038</p> <p>Piston Not included</p> |  <p>1R12-093</p> | <p>ASA-92-8-164</p>  | <p>Use existing piston</p> | <p>Service Assembly for 1R12-092 is the 1R12-092 without the piston.</p> <p>Use only with Goodyear pistons.</p> |

- - Bolt or Stud - 1/2-13 or 1/2-20
- ⊗ - Air Fitting - 1/4 NPTF
- - Stud - 3/4-10
- ⊕ - Tapped Hole on Top Retainers 3/8-16, on Pistons - 1/2-13
- ⊗ - Air Fitting - 1/2 NPTF 3/8 NPTF
- ⊗ - Combination Stud Air Fitting Stud - 3/4-16; Air Fitting - 1/4 NPTF