
















GOODYEAR PART NO.	Side View With Extended and Compressed Height	Upper Mounting View	Lower Mounting View	Replaces These Springs
2B12-307 Flexmember 578-92-3-305		ASA-92-8-017 	AS1-92-6-002 	Dayton 354-7403 Firestone 7403 Granning 2725 HDA PMABG-7403B Hendrickson B-1159 B-2883 Load Guard SC2021 Navistar 554787C1 Ridewell S-4302C R&S Truck Taurus 1040201 1090201 Taurus AS214-7403 Triangle 4318 Watson &Chalin AS0007, -0068
2B12-309 Flexmember 578-92-3-309		578-92-8-002 	578-92-6-002 	Dayton 354-7400 Firestone 7400 Freightliner 16-10796 GMC 693230 Granning 2726 Hendrickson C-1013 Load Guard Navistar SC2020 554788C1 Neway TC-144-4 90557016 R&S Truck 1027519 Ridewell S-788-C 1003587400C Watson &Chalin AS-0003
2B12-313 Flexmember 578-92-3-309		ASA-92-8-004 	ASA-92-6-004 	Dayton 354-7405 Firestone 7405 Hutchens 10384-01 Load Guard SC2073 Navistar 1685177C1 Susp., Inc. 200981 Taurus AS214-7405 Triangle 4364
2B12-317 Flexmember 578-92-3-310		ASA-92-8-004 	ASA-92-6-004 	Chalmers Firestone 7185 7499 Suspensions, Inc. Triangle 4502
2B12-318 Flexmember 578-92-3-309		AS1-92-8-006 	AS1-92-6-002 	Chalmers Firestone 7185