
















# BELLOWS STYLE

GOODYEAR PART NO.	Side View With Extended and Compressed Height	Upper Mounting View	Lower Mounting View	Replaces These Springs	
<b>2B12-319</b>  Flexmember 578-92-3-309		<b>ASA-92-8-005</b> 	<b>ASA-92-6-004</b> 	<b>Dayton</b> 354-7409 <b>Firestone</b> 7409 <b>Fruehauf</b> <b>Load Guard</b> SC2074 <b>Navistar</b> 1685178C1 <b>Taurus</b> AS214-7409 <b>Triangle</b> 4367	<b>Watson &amp;Chalin</b> AS-0093
<b>2B12-320</b>  Flexmember 578-92-3-309		<b>ASA-92-8-003</b> 	<b>ASA-92-6-004</b> 	<b>Dayton</b> 354-7437 <b>Firestone</b> 7401, 7437 <b>GMC</b> 711954 <b>HDA</b> PMABG-7401B <b>Load Guard</b> SC2025 <b>Navistar</b> 554789C1	<b>Neway</b> TC-144-3A 90557015 <b>Ridewell</b> S-3363-C 1006587437C <b>Volvo / GM</b> 2076095 <b>Triangle</b> 4334, 4337 <b>Watson &amp;Chalin</b> AS-0014
<b>2B12-324</b>  Flexmember 578-92-3-310		<b>ASA-92-8-017</b> 	<b>ASA-92-6-002</b> 	<b>Allison</b> <b>Dayton</b> 354-7447 <b>E-Z Ride</b> 8030150 <b>Firestone</b> 7447, 7790 <b>Hendrickson</b> B-6242 <b>Load Guard</b> SC2028 <b>Navistar</b> 554790C1	<b>Triangle</b> 4340, 4513
<b>2B12-340</b>  Flexmember 578-92-3-309		<b>ASB-92-9-153</b> 	<b>ASB-92-9-153</b> 		
<b>2B12-345</b>  Flexmember 578-92-3-315		<b>ASA-92-8-005</b> 	<b>ASA-92-6-002</b> 	<b>Firestone</b> 7545 <b>Triangle</b> 4514	

- - Bolt or Stud - 1/2-13 or 1/2-20
- ⊗ - Air Fitting - 1/4 NPTF
- ⊙ - Stud - 3/4-10
- ⊕ - Tapped Hole on Top Retainers
- ⊗ - Air Fitting - 1/2 NPTF
- ⊗ - Combination Stud Air Fitting
- 3/8-16, on Pistons - 1/2-13
- 3/8 NPTF
- Stud - 3/4-16; Air Fitting - 1/4 NPTF