
















# BELLOWS STYLE

GOODYEAR PART NO.	Side View With Extended and Compressed Height	Upper Mounting View	Lower Mounting View	Replaces These Springs	
<b>2B12-412</b>  Flexmember 578-92-3-309		<b>ASA-92-8-088</b> 	<b>ASA-92-6-038</b> 	<b>Dayton</b> 354-7183 <b>Firestone</b> 7183 <b>Fruehauf</b> UCA-0112 UCA-0112B <b>Load Guard</b> SC2019 <b>Navistar</b> 554795C1 <b>Taurus</b> AS214-7183	<b>Triangle</b> 4471
<b>2B12-416</b>  Flexmember 578-92-3-315		<b>AS1-92-8-002</b> 	<b>ASA-92-6-002</b> 	<b>Firestone</b> 7444 <b>Hendrickson</b> B-9830 <b>Triangle</b> 4369	
<b>2B12-425</b>  Flexmember 578-92-3-309		<b>AS1-92-8-002</b> 	<b>ASA-92-6-002</b> 	<b>EZ Ride</b> 8030190 <b>Firestone</b> 7180 <b>Hendrickson</b>  <b>International</b> 1685779C1 <b>Kwik-Lok</b>  <b>Load Guard</b> SC-2075	<b>Peerless</b> 0550-00001 <b>Ridewell</b> S-4538-C <b>Taurus</b> AS214-7180 <b>Talbert</b>  <b>Triangle</b> 4363
<b>2B12-426</b>  Flexmember 578-92-3-309		<b>ASA-92-8-003</b> 	<b>ASA-92-6-002</b> 	<b>Dayton</b> 354-7406 <b>Firestone</b> 7406 <b>Load Guard</b> SC2076 <b>Navistar</b> 1685180C1 <b>Ridewell</b> S-3159C 1003587406C <b>Taurus</b> AS214-7406	<b>Triangle</b> 4365
<b>2B12-427</b>  Flexmember 578-92-3-309		<b>ASA-92-8-004</b> 	<b>ASA-92-6-002</b> 	<b>Dayton</b> 354-7429 <b>Firestone</b> 7429 <b>KwikLok/Todco (Jifflox)</b> CP-5223 <b>Load Guard</b> SC2077 <b>Navistar</b> 1685181C1 <b>Silent Drive</b>	<b>Taurus</b> AS214-7429 <b>Triangle</b> 4343

- - Bolt or Stud - 1/2-13 or 1/2-20
- ⊗ - Air Fitting - 1/4 NPTF
- ⊙ - Stud - 3/4-10
- ⊕ - Tapped Hole on Top Retainers
- ⊗ - Air Fitting - 1/2 NPTF
- ⊗ - Combination Stud Air Fitting
- 3/8-16, on Pistons - 1/2-13
- 3/8 NPTF
- Stud - 3/4-16; Air Fitting - 1/4 NPTF