
















| GOODYEAR PART NO. | Side View With Extended and Compressed Height | Upper Mounting View | Lower Mounting View | Replaces These Springs |
|--|---|---|--|---|
| 2B12-428 Flexmember 578-92-3-310 |  | AS1-92-8-002  | ASA-92-6-002  | Firestone 7473 Load Guard SC2078 Navistar 1685182C1 Ridewell 1003587473C Triangle 4372 |
| 2B12-429 Flexmember 578-92-3-309 |  | AS1-92-8-006  | ASA-92-6-002  | Firestone 8184 |
| 2B12-432 Flexmember 578-92-3-309 |  | ASA-92-8-005  | AS1-92-6-001  | Firestone 7423 Load Guard SC2101 Navistar 1681750C1 Sauer Axles P10-784 Triangle 4368 |
| 2B12-434 Flexmember 578-92-3-310 |  | ASA-92-8-017  | ASA-92-6-000  | Firestone 7472 Hendrickson 36514-5 Load Guard SC2128 Navistar 1681751C1 Triangle 4371 |
| 2B12-440 Flexmember 578-92-3-315 |  | ASA-92-8-005  | ASA-92-6-004  | Firestone 7550 7555 Reyco 18813-01 20018-01 Triangle 4480 Watson & Chalin AS-0087 |