
















GOODYEAR PART NO.	Side View With Extended and Compressed Height	Upper Mounting View	Lower Mounting View	Replaces These Springs
2B9-210 Flexmember 578-92-3-202		578-92-8-040 	ASA-92-6-010 	Firestone 6908 Triangle 4362 Watson & Chalin AS-0035
2B9-218 Flexmember 578-92-3-206		ASA-92-8-113 	ASA-92-6-010 	Firestone 6927 Langes Load Guard SC2072 Navistar 1685176C1 Reyco 12906-01 12906-02 Taurus AS218-6927 Triangle 4453
2B9-225 Flexmember 578-92-3-202		ASA-92-8-117 	ASA-92-6-044 	Misner Brake System Thraul Davis Rail Car
2B9-229 Flexmember 578-92-3-202		ASA-92-8-113 	ASA-92-6-077 	Firestone 6897 Triangle 4505 Watson & Chalin AS-0058
2B9-230 Flexmember 578-92-3-202		ASA-92-8-113 	ASA-92-6-044 	Firestone 6940 Langes Triangle 4450