
















GOODYEAR PART NO.	Side View With Extended and Compressed Height	Upper Mounting View	Lower Mounting View	Replaces These Springs
2B9-252 Flexmember 578-92-3-206		ASA-92-8-172 	ASA-92-6-044 	Firestone 6941 HISTEER 10302 Langes Load Guard SC2124 Suspensions, Inc. 200118 Triangle 4448
2B9-253 Flexmember 578-92-3-206		AS1-92-8-040 	ASA-92-6-010 	Firestone 6945 Load Guard SC2125 Ridewell 1003586945C Triangle 4427
2B9-254 Flexmember 578-92-3-206		ASA-92-8-172 	ASA-92-6-010 	Firestone 6946, 6962 Hendrickson B-21323 Load Guard SC2126 Ridewell 1003586946C Suspensions, Inc. 200180 Triangle 4463, 4511
2B9-255 Flexmember 578-92-3-206		ASA-92-8-016 	ASA-92-6-010 	Dayton 354-6947 Firestone 6947 Hendrickson B-8701 Load Guard SC2127 Ridewell 1006586947C Triangle 4428
2B9-265 Flexmember 578-92-3-206		ASA-92-8-270 	ASA-92-6-044 	Firestone 6941 HISTEER 10302