
















GOODYEAR PART NO.	Side View With Extended and Compressed Height	Upper Mounting View	Lower Mounting View	Replaces These Springs
<b>2B9-252</b>  <b>Flexmember</b> 578-92-3-206		<b>ASA-92-8-172</b> 	<b>ASA-92-6-044</b> 	<b>Firestone</b> 6941 <b>HISTEER</b> 10302 <b>Langes</b>  <b>Load Guard</b> SC2124 <b>Suspensions, Inc.</b> 200118 <b>Triangle</b> 4448
<b>2B9-253</b>  <b>Flexmember</b> 578-92-3-206		<b>AS1-92-8-040</b> 	<b>ASA-92-6-010</b> 	<b>Firestone</b> 6945 <b>Load Guard</b> SC2125 <b>Ridewell</b> 1003586945C <b>Triangle</b> 4427
<b>2B9-254</b>  <b>Flexmember</b> 578-92-3-206		<b>ASA-92-8-172</b> 	<b>ASA-92-6-010</b> 	<b>Firestone</b> 6946, 6962 <b>Hendrickson</b> B-21323 <b>Load Guard</b> SC2126 <b>Ridewell</b> 1003586946C <b>Suspensions, Inc.</b> 200180 <b>Triangle</b> 4463, 4511
<b>2B9-255</b>  <b>Flexmember</b> 578-92-3-206		<b>ASA-92-8-016</b> 	<b>ASA-92-6-010</b> 	<b>Dayton</b> 354-6947 <b>Firestone</b> 6947 <b>Hendrickson</b> B-8701 <b>Load Guard</b> SC2127 <b>Ridewell</b> 1006586947C <b>Triangle</b> 4428
<b>2B9-265</b>  <b>Flexmember</b> 578-92-3-206		<b>ASA-92-8-270</b> 	<b>ASA-92-6-044</b> 	<b>Firestone</b> 6941 <b>HISTEER</b> 10302