















GOODYEAR PART NO.	Side View With Extended and Compressed Height	Upper Mounting View	Lower Mounting View	Replaces These Springs
<b>3B14-354</b>  Flexmember 578-93-3-350		<b>ASA-92-8-028</b> 	<b>ASA-92-6-013</b> 	<b>Firestone</b> 7808 <b>Load Guard</b> SC2031 <b>Navistar</b> 554801C1 <b>Peerless</b> 0550-00030 <b>Ridewell</b> S-4830C 1003587808C <b>Triangle</b> 4336
<b>3B14-356</b>  Flexmember 578-93-3-350		<b>ASA-92-8-028</b> 	<b>ASA-92-6-013</b> 	<b>Allison</b> <b>Dayton</b> 354-7798 <b>E-Z Ride</b> 8030170 <b>Firestone</b> 7798 7838 <b>Granning</b> 1613 <b>HDA</b> PMABG-7798B <b>Load Guard</b> SC2029 <b>Navistar</b> 554802C1 <b>R&amp;S Truck</b> 1090023 <b>Triangle</b> 4329 <b>Watson &amp;Chalin</b> AS-0006
<b>3B14-359</b>  Flexmember 578-93-3-350		<b>ASA-92-8-031</b> 	<b>ASA-92-6-015</b> 	<b>Dayton</b> 354-7818 354-7839 <b>E-Z Ride</b> 8030180 <b>Firestone</b> 7818, 7839 <b>Granning</b> 1014, 1476 <b>Hendrickson</b> B-6861 <b>Langes</b> <b>Porcupine</b> <b>Load Guard</b> SC2032 <b>Navistar</b> 554803C1 <b>Ridewell</b> S-2685C 1003587819C 1003587839C <b>Triangle</b> 4325 <b>Watson &amp;Chalin</b> AS-0025 AS-0033
<b>3B14-360</b>  Flexmember 578-93-3-350		<b>ASA-92-8-031</b> 	<b>ASA-92-6-015</b> 	<b>Dayton</b> 354-7800 <b>Firestone</b> 7800 7848 <b>Granning</b> 4514 <b>Holland</b> <b>Hitch</b> 4514 <b>Load Guard</b> SC2030 <b>Navistar</b> 554804C1 <b>Ridewell</b> S-1505C 1003587800C <b>Silent Drive</b> <b>Superior</b> <b>Triangle</b> 4333
<b>3B14-361</b>  Flexmember 578-93-3-350  Replaces 3B14-352		<b>ASA-92-8-030</b> 	<b>ASA-92-6-013</b> 