

GOODYEAR PART NO.	Side View With Extended and Compressed Height	Upper Mounting View	Lower Mounting View	Replaces These Springs
1R10-089 Flexmember 566-20-3-021 Piston 566-20-7-240 Composite	<p>23.1 8.0</p>	ASA-92-8-151 <p>4.76 9.00</p>	<p>4.12 9.27</p>	Auto Bus 684193 10530087 684195-3 Firestone 8870485 9017 8875032 Flexible 10530087 6-304-157 Novabus 6-336-174 N15558 6-841-92 Prevost 97-240-153 63-0044 GMC 63-0093 661756 677302 684192
1R10-091 Flexmember 566-20-3-021 Piston 566-20-7-240 Composite	<p>20.1 8.1</p>	ASA-92-8-152 <p>4.76 9.00</p>	<p>4.12 9.27</p>	Firestone 9380 Prevost 63-0067
1R10-120 Flexmember 566-20-3-021 Piston 566-20-7-240 Composite	<p>20.1 7.1</p>	ASA-92-8-162 <p>5.50 9.00</p>	<p>9.27</p>	Firestone 9293 Neway 90557120 Triangle 8424
1R10-122 Flexmember 566-20-3-021 Piston 566-20-7-237 Composite	<p>22.1 9.1</p>	ASA-92-8-162 <p>5.50 9.00</p>	<p>9.80</p>	Firestone 9291 Neway 90557122 90557139 Triangle 8425 Replaces 1R11-172
1R11-018 Flexmember 566-22-3-006 Piston 566-20-7-079 Steel	<p>18.5 7.2</p>	AS3-20-8-003 <p>4.76 7.50</p>	<p>4.12 10.12</p>	Circle R Load Guard Dayton SC2049 352-9073 Navistar 352-9415 554761C1 Firestone Ridewell 9073 1003589073C 9415 1013580708C Hendrickson Taurus B-7193 AS103-9073 Kenworth Triangle K-102-A 8322 K-303-5