

ROLLING LOBE STYLE

GOODYEAR PART NO.	Side View With Extended and Compressed Height	Upper Mounting View	Lower Mounting View	Replaces These Springs
1R11-151 Flexmember 566-22-3-021 Piston 566-20-7-055 Aluminum	<p>13.0 4.7</p> <p>1R11-151</p>	ASA-92-8-162 <p>5.50 9.00</p>	<p>4.12 8.60</p>	Firestone 9457 Ridewell 1003589457C
1R11-152 Flexmember 566-22-3-021 Piston 566-20-7-055 Aluminum	<p>13.0 4.7</p> <p>1R11-152</p>	ASA-92-8-162 <p>5.50 9.00</p>	<p>8.60</p>	Firestone 9459
1R11-159 Flexmember 566-22-3-021 Piston 566-20-7-014 Steel	<p>13.0 4.4</p> <p>1R11-159</p>	ASA-92-8-162 <p>5.50 9.00</p>	<p>9.25</p>	
1R11-161 Flexmember 566-22-3-057 Piston 566-20-7-150 Steel	<p>12.0 5.8</p> <p>1R11-161</p>	ASA-92-8-115 <p>5.50 9.00</p>	<p>8.25</p>	American Carrier 8003-023 Firestone 5766 Hutchens 19141-01
1R11-162 Flexmember 566-22-3-021 Piston 566-20-7-014 Steel	<p>11.9 3.8</p> <p>1R11-162</p>	ASA-92-8-164 <p>5.50 9.00</p>	<p>9.25</p>	