














ROLLING LOBE STYLE

GOODYEAR PART NO.	Side View With Extended and Compressed Height	Upper Mounting View	Lower Mounting View	Replaces These Springs
1R11-151 Flexmember 566-22-3-021 Piston 566-20-7-055 Aluminum		ASA-92-8-162 		Firestone 9457 Ridewell 1003589457C
1R11-152 Flexmember 566-22-3-021 Piston 566-20-7-055 Aluminum		ASA-92-8-162 		Firestone 9459
1R11-159 Flexmember 566-22-3-021 Piston 566-20-7-014 Steel		ASA-92-8-162 		
1R11-161 Flexmember 566-22-3-057 Piston 566-20-7-150 Steel		ASA-92-8-115 		American Carrier 8003-023 Firestone 5766 Hutchens 19141-01
1R11-162 Flexmember 566-22-3-021 Piston 566-20-7-014 Steel		ASA-92-8-164 