
















## ROLLING LOBE STYLE

GOODYEAR PART NO.	Side View With Extended and Compressed Height	Upper Mounting View	Lower Mounting View	Replaces These Springs
<b>1R12-256</b>  <b>Flexmember</b> 566-24-3-090  <b>Piston</b> 566-20-7-159 Composite		<b>ASA-92-8-142</b> 		<b>Firestone</b> 9367 <b>Hendrickson</b> B-14249 B-4375 <b>Load Guard</b> SC2120 <b>Suspensions</b> Inc. 201335 <b>Triangle</b> 8505  <b>Watson &amp;Chalin</b> AS-0104
<b>1R12-261</b>  <b>Flexmember</b> 566-24-3-066  <b>Piston</b> 566-20-7-006 Aluminum		<b>ASA-92-8-005</b> 		<b>Firestone</b> 9241 <b>R &amp; S Truck and Body</b> 10907 <b>Triangle</b> 8358 8361
<b>1R12-265</b>  <b>Flexmember</b> 566-24-3-066  <b>Piston</b> 566-20-7-080 Composite		<b>ASA-92-8-164</b> 		<b>Firestone</b> 9204 9245 <b>Triangle</b> 8390 8506 <b>Watson &amp; Chalin</b> AS-0031
<b>1R12-274</b>  <b>Flexmember</b> 566-24-3-097  <b>Piston</b> 566-20-7-079 Steel		<b>AS3-92-8-121</b> 	<b>AS4-20-7-079</b> 	
<b>1R12-279</b>  <b>Flexmember</b> 566-24-3-066  <b>Piston</b> 566-20-7-080 Composite		<b>ASA-92-8-121</b> 		<b>Firestone</b> 9394 <b>Fruehauf</b> UCE-9393-2 <b>Triangle</b> 8383