

# ROLLING LOBE STYLE

GOODYEAR PART NO.	Side View With Extended and Compressed Height	Upper Mounting View	Lower Mounting View	Replaces These Springs
<b>1R13-115</b>  <b>Flexmember</b> 566-26-3-044  <b>Piston</b> 566-20-7-006 Aluminum	<p>27.0 9.4</p>	<b>ASA-92-8-004</b> <p>5.50 9.00</p>	<p>7.87 10.13</p>	<b>Firestone</b> 9250 <b>Ridewell</b> 1003589250C <b>Silent Drive Triangle</b> 8324 <b>Watson &amp; Chalin</b> AS-0096
<b>1R13-116</b>  <b>Flexmember</b> 566-26-3-044  <b>Piston</b> 566-20-7-006 Aluminum	<p>27.0 8.9</p>	<b>ASA-92-8-004</b> <p>5.50 9.00</p>	<p>7.87 10.13</p>	<b>Firestone</b> 9252 <b>Ridewell</b> 1003589252C <b>Triangle</b> 8363
<b>1R13-117</b>  <b>Flexmember</b> 566-26-3-043  <b>Piston</b> 566-20-7-080 Composite	<p>23.2 7.7</p>	<b>ASA-92-8-004</b> <p>5.50 9.00</p>	<p>7.87 10.10</p>	<b>Firestone</b> 9275 <b>Ridewell</b> 1003589275C <b>Triangle</b> 8323
<b>1R13-118</b>  <b>Flexmember</b> 566-26-3-034  <b>Piston</b> 566-20-7-127 Steel	<p>25.0 7.2</p>	<b>ASA-92-8-192</b> <p>3.05 9.00</p>	<p>5.66 10.20</p>	<b>Firestone</b> 9262 9580 <b>Hendrickson</b> C20127 <b>Triangle</b> 8434  Replaces 1R13-081
<b>1R13-119</b>  <b>Flexmember</b> 566-26-3-053 or 26-3-036  <b>Piston</b> 566-20-7-106 Steel	<p>18.0 5.6</p>	<b>AS1-92-8-235</b> <p>1.83 2.45 3.05 9.00</p>	<p>5.66 9.50</p>	<b>Firestone</b> 9270 <b>Hendrickson</b> C20010 C21208 <b>Triangle</b> 8433 <b>Watson &amp; Chalin</b> AS-0084

- - Bolt or Stud - 1/2-13 or 1/2-20
- ⊗ - Air Fitting - 1/4 NPTF
- - Stud - 3/4-10
- ⊕ - Tapped Hole on Top Retainers
- ⊗ - Air Fitting - 1/2 NPTF
- ⊗ - Combination Stud Air Fitting
- 3/8-16, on Pistons - 1/2-13
- 3/8 NPTF
- Stud - 3/4-16; Air Fitting - 1/4 NPTF