
















BELLOWS STYLE

GOODYEAR PART NO.	Side View With Extended and Compressed Height	Upper Mounting View	Lower Mounting View	Replaces These Springs
2B12-319 Flexmember 578-92-3-309		ASA-92-8-005 	ASA-92-6-004 	Dayton 354-7409 Firestone 7409 Fruehauf Load Guard SC2074 Navistar 1685178C1 Taurus AS214-7409 Triangle 4367 Watson &Chalin AS-0093
2B12-320 Flexmember 578-92-3-309		ASA-92-8-003 	ASA-92-6-004 	Dayton 354-7437 Firestone 7401, 7437 GMC 711954 HDA PMABG-7401B Load Guard SC2025 Navistar 554789C1 Neway TC-144-3A 90557015 Ridewell S-3363-C 1006587437C Volvo / GM 2076095 Triangle 4334, 4337 Watson &Chalin AS-0014
2B12-324 Flexmember 578-92-3-310		ASA-92-8-017 	ASA-92-6-002 	Allison Dayton 354-7447 E-Z Ride 8030150 Firestone 7447, 7790 Hendrickson B-6242 Load Guard SC2028 Navistar 554790C1 Triangle 4340, 4513
2B12-340 Flexmember 578-92-3-309		ASB-92-9-153 	ASB-92-9-153 	
2B12-345 Flexmember 578-92-3-315		ASA-92-8-005 	ASA-92-6-002 	Firestone 7545 Triangle 4514

- - Bolt or Stud - 1/2-13 or 1/2-20
- ⊕ - Tapped Hole on Top Retainers
- ⊗ - Air Fitting - 1/4 NPTF
- ⊗ - Air Fitting - 1/2 NPTF
- ⊗ - Air Fitting - 3/8 NPTF
- - Stud - 3/4-10
- ⊗ - Combination Stud Air Fitting
- - Stud - 3/4-16; Air Fitting - 1/4 NPTF