
















GOODYEAR PART NO.	Side View With Extended and Compressed Height	Upper Mounting View	Lower Mounting View	Replaces These Springs
2B12-346  Flexmember 578-92-3-315		ASA-92-8-005 	ASA-92-6-002 	Firestone 7550 Triangle 4541
2B12-402  Flexmember 578-92-3-310		ASA-92-8-005 	ASA-92-6-002 	Dayton 354-7446 Firestone 7446 HDA PMABG-7446B Hendrickson B-3798 Load Guard SC2027 Navistar 554791C1  R&S Truck 1082914 Triangle 4370 Watson &Chalin AS-0005
2B12-406  Flexmember 578-92-3-309		ASA-92-8-005 	ASA-92-6-002 	Dayton 354-7446 Firestone 7410 Freightliner 16-11378 Load Guard SC2023 Navistar 554792C1 Taurus AS214-7410  Triangle 4331
2B12-410  Flexmember 578-92-3-309		ASA-92-8-017 	ASA-92-6-001 	Dayton 354-7404 Firestone 7404 Hendrickson B-1345 B-5468 Load Guard SC2022 Navistar 554793C1 Taurus AS214-7404  Triangle 4346
2B12-411  Flexmember 578-92-3-309		ASA-92-8-088 	ASA-92-6-006 	Dayton 354-7181 Firestone 7181 Fruehauf UAB-5620 UCC-3054-1 Load Guard SC2018 Navistar 554794C1 Taurus AS214-7181  Triangle 4472