
















GOODYEAR PART NO.	Side View With Extended and Compressed Height	Upper Mounting View	Lower Mounting View	Replaces These Springs
2B12-428 Flexmember 578-92-3-310		AS1-92-8-002 	ASA-92-6-002 	Firestone 7473 Load Guard SC2078 Navistar 1685182C1 Ridewell 1003587473C Triangle 4372
2B12-429 Flexmember 578-92-3-309		AS1-92-8-006 	ASA-92-6-002 	Firestone 8184
2B12-432 Flexmember 578-92-3-309		ASA-92-8-005 	AS1-92-6-001 	Firestone 7423 Load Guard SC2101 Navistar 1681750C1 Sauer Axles P10-784 Triangle 4368
2B12-434 Flexmember 578-92-3-310		ASA-92-8-017 	ASA-92-6-000 	Firestone 7472 Hendrickson 36514-5 Load Guard SC2128 Navistar 1681751C1 Triangle 4371
2B12-440 Flexmember 578-92-3-315		ASA-92-8-005 	ASA-92-6-004 	Firestone 7550 7555 Reyco 18813-01 20018-01 Triangle 4480 Watson & Chalin AS-0087