
















GOODYEAR PART NO.	Side View With Extended and Compressed Height	Upper Mounting View	Lower Mounting View	Replaces These Springs
2B14-473 Flexmember 578-92-3-353		ASA-92-8-046 	ASA-92-6-014 	
2B14-476 Flexmember 578-92-3-356		ASA-92-8-352 	ASA-92-6-016 	<u>Firestone</u> 6799 <u>Neway</u> 90557203
3B12-300 Flexmember 578-93-3-100		ASA-92-8-017 	ASA-92-6-002 	<u>Dayton</u> 354-8008 <u>E-Z Ride</u> <u>Firestone</u> 8008 8025 <u>Hendrickson</u> B-11637 <u>Langes</u> <u>Load Guard</u> SC2130 <u>Ridewell</u> 1003588008C <u>Silent Drive</u> <u>Triangle</u> 4431 4469 <u>Watson & Chalin</u> AS-0019
3B12-301 Flexmember 578-93-3-100		ASA-92-8-002 	ASA-92-6-002 	<u>Firestone</u> 8010 8030 <u>Load Guard</u> SC2119 <u>Ridewell</u> S-5844C 1003588010C <u>Tafco</u> <u>Triangle</u> 4432 4498
3B12-303 Flexmember 578-93-3-100		ASA-92-8-005 	ASA-92-6-002 	<u>Firestone</u> 8018 8027 <u>HISTEER</u> 10303 <u>Langes</u> <u>Load Guard</u> SC2131 <u>Triangle</u> 4434 4466 <u>Watson & Chalin</u> AS-0075