
















GOODYEAR PART NO.	Side View With Extended and Compressed Height	Upper Mounting View	Lower Mounting View	Replaces These Springs
2B14-473  Flexmember 578-92-3-353		ASA-92-8-046 	ASA-92-6-014 	
2B14-476  Flexmember 578-92-3-356		ASA-92-8-352 	ASA-92-6-016 	<b>Firestone</b> 6799 <b>Neway</b> 90557203
3B12-300  Flexmember 578-93-3-100		ASA-92-8-017 	ASA-92-6-002 	<b>Dayton</b> 354-8008 <b>E-Z Ride</b>  <b>Firestone</b> 8008 8025 <b>Hendrickson</b> B-11637 <b>Langes</b> Load Guard SC2130  <b>Ridewell</b> 1003588008C <b>Silent Drive</b>  <b>Triangle</b> 4431 4469 <b>Watson &amp; Chalin</b> AS-0019
3B12-301  Flexmember 578-93-3-100		ASA-92-8-002 	ASA-92-6-002 	<b>Firestone</b> 8010 8030 <b>Load Guard</b> SC2119 <b>Ridewell</b> S-5844C 1003588010C <b>Tafco</b>  <b>Triangle</b> 4432 4498
3B12-303  Flexmember 578-93-3-100		ASA-92-8-005 	ASA-92-6-002 	<b>Firestone</b> 8018 8027 <b>HISTEER</b> 10303 <b>Langes</b>  <b>Load Guard</b> SC2131 <b>Triangle</b> 4434 4466  <b>Watson &amp; Chalin</b> AS-0075