
















# BELLOWS STYLE

GOODYEAR PART NO.	Side View With Extended and Compressed Height	Upper Mounting View	Lower Mounting View	Replaces These Springs
<b>3B12-304</b>  Flexmember 578-93-3-100		<b>ASA-92-8-002</b> 	<b>ASA-92-6-000</b> 	<b>Firestone</b> 8006 <b>Load Guard</b> SC2132 <b>Superior</b>  <b>Suspensions, Inc.</b> 200620 <b>Triangle</b> 4430 4503
<b>3B12-310</b>  Flexmember 578-93-3-100		<b>ASA-92-8-005</b> 	<b>ASA-92-6-002</b> 	<b>Firestone</b> 8027 <b>HISTEER</b>  <b>Silent Drive</b>  <b>Suspensions, Inc.</b> 200117 <b>Triangle</b> 4466
<b>3B12-312</b>  Flexmember 578-93-3-100		<b>ASA-92-8-005</b> 	<b>AS1-92-6-035</b> 	<b>Firestone</b> 8033 <b>Hendrickson</b> B-14487 <b>Triangle</b> 4508 4525
<b>3B12-315</b>  Flexmember 578-93-3-100		<b>ASA-92-8-017</b> 	<b>ASA-92-6-002</b> 	<b>Firestone</b> 8032 <b>Watson &amp; Chalin</b> AS-0048
<b>3B12-319</b>  Flexmember 578-93-3-100		<b>ASA-92-8-017</b> 	<b>ASA-92-6-002</b> 	<b>Firestone</b> 8032 <b>Triangle</b> 4413

- - Bolt or Stud - 1/2-13 or 1/2-20
- ⊕ - Tapped Hole on Top Retainers
- ⊗ - Air Fitting - 1/4 NPTF
- ⊗ - Air Fitting - 1/2 NPTF
- ⊗ - Air Fitting - 3/8 NPTF
- - Stud - 3/4-10
- ⊗ - Combination Stud Air Fitting
- ⊗ - Stud - 3/4-16; Air Fitting - 1/4 NPTF