
















GOODYEAR PART NO.	Side View With Extended and Compressed Height	Upper Mounting View	Lower Mounting View	Replaces These Springs
<b>3B12-322</b>  Flexmember 578-93-3-103		<b>ASA-92-8-230</b> 	<b>ASA-92-6-110</b> 	<b>Firestone</b> 8042
<b>3B12-323</b>  Flexmember 578-93-3-103		<b>ASA-92-8-367</b> 	<b>ASA-92-6-110</b> 	<b>Firestone</b> 8043
<b>3B12-324</b>  Flexmember 578-93-3-100		<b>ASA-92-8-159</b> 	<b>ASA-92-6-002</b> 	<b>Watson &amp; Chalin</b> AS0048-2G
<b>3B12-325</b>  Flexmember 578-93-3-103		<b>ASA-92-8-363</b> 		<b>Firestone</b> 8048
<b>3B12-326</b>  Flexmember 578-93-3-103		<b>ASA-92-8-364</b> 		<b>Firestone</b> 8047